

## Coach #20 Windows Repair

The following information was extrapolated from Facebook posts in whole or in part.

### January 26, 2025: Included these two photos.

Eric Wunz posted *“The new oak windows for Coach #20 are half done. 28 more to go in Feb. The old ones were 35 years old, stained, and falling apart”.*



### March 14, 2025: Included the next two photos.

Eric Wunz posted *“Had to replace over half of the wood arches above the windows on Coach #20. Old ones were falling apart. Have the new arches and the upper windows in.”*

*The mahogany pieces that hold the lower windows were sun and water damaged and needed to be sanded and revarnished. Took them home to do that and they will be ready on Sunday to install the lower windows”.*



Taylor Rush wrote *“You’ve been keeping her interior looking good for what, 35 years now”?*

Bryan Cooper wrote *“Thanks for all your hard work Eric. You are a rock star”!*

Jerry Holmes wrote *“Your continuing hard work is greatly appreciated”.*

### March 19, 2025: Included one photo on right.

Eric Wunz posted *“Have half the windows and their trim installed in Coach #20”.*

**Editor’s Note:** The old windows being replaced now have lasted 35 years in large part to Eric’s woodworking skills and knowledge of our quirky equipment. Beautiful!



### March 30, 2025: Included the three photos below.

Eric Wunz posted *“There is often mission creep when restoring old equipment. The window sills were sun and water damaged and needed sanding and varnishing. Now looking at replacing the outside wood pieces between the windows as they are badly deteriorated”.*



### April 10, 2025: Included the photo on right.

Eric Wunz posted *“About 3/4 done replacing the outside wood between the windows. Still need to mill up the vertical trim boards and install them and finish painting.”*

*Taking a week off and plan on completing it by end of April”.*



**April 26, 2025: Included the two photos at right.**

Eric Wunz posted *“Back working on Coach #20, all the outside trim is on and 2 coats of paint on the trim. One more coat of paint on the outside and it will be done.*

*The seats still need sanding and varnishing, and the floor can use painting too. Any volunteers”?*



**May 11, 2025: Included the last photo.**

Kim Svaty posted (no caption) this photo of Eric Wunz working on a clerestory window.

